



PORT OPERATIONS

Local Notice to Mariners 01/20 (Revision 5)

Tide buoys

Mariners are advised that due to storm damage the AADI (electronic current information from the buoy) is unavailable at the Eastern entrance. **This Buoy has been removed for repairs.**

The other tide buoy (with the tide tails) has now been redeployed just East of the AADI buoy's position to avoid encroaching on the entrance.

In the interim, BA chart 1698 gives information on the predicted tidal streams at the Eastern entrance.

Steve Masters
Harbour Master

27th May 2020

Notices Remaining In Force:

- 08/19 – Decommissioned mooring equipment
- 23/19 - DWDR restricted Area
- 50/19 - Temporary Suspension of the Wick Channel Traffic Lights
- 68/19 – Structural Damage Pier Bravo
- 01/20 - Tide buoys (Revised)
- 16/20 - North East unlighted Buoy off Station
- 32/20 - Diving Operations ED7 Landward end
- 35/20 – Lost Anchor Eastern Docks
- 40/20 – Diving Operations Wick Channel