



## PORT OPERATIONS

### **Notice to Mariners 55/16**

#### **Admiralty Pier HIL inoperable**

Mariners are advised that the High Intensity Light (HIL) on the Admiralty Pier, at the Western Entrance, is currently inoperable.

The Navigation Light (Fl 7.5s 20m/20M) continues to function normally.

Mariners are advised to proceed with caution at times of reduced visibility at the Western Entrance.

Work to restore normal operation will be completed as soon as possible.

Paul Brown  
Harbour Master

30<sup>th</sup> October 2016

#### **Notices Remaining In Force:**

- 7/15 – ED3 Extension Side Fender Temp Removal (amended)
- 54/15 – Coralwater Tidal Restriction
- 70/15 – Pier Alpha Nav Lt reinstated. HIL and Fog Signal Unserviceable (updated)
- 02/16 – Leisure Zone Special Mark Buoy (amended)
- 15/16 – Buoys marking swimming area
- 17/16 – Buoys marking DWDR exclusion zone
- 40/16 – Decommissioned mooring equipment
- 46/16 – Granville Dock Marina depths
- 49/16 – PD5
- 52/16 – Western Docks Firework Display 04/11/2016
- 55/16 – Admiralty Pier HIL