



## PORT OPERATIONS

### **Local Notice to Mariners 66/20**

#### **ED7 Stern Fenders**

Mariners are advised that ED7 Stern fenders have sustained damage to the lower section and rubber mountings. Vessels using ED7 must land with caution at slow speed until repairs have been affected.

Sarah West  
Harbour Master

13<sup>th</sup> November 2020

#### **Notices Remaining In Force:**

08/19 – Decommissioned mooring equipment  
68/19 – Structural Damage Pier Bravo  
01/20 - Tide buoys (Revised)  
35/20 - Lost Anchor Eastern Docks  
53/20 – Pier C dolphin  
58/20 – POWP lighthouse change of colour  
65/20 - Wick Channel Obstruction  
66/20 – ED7 Stern Fenders