




PORT OPERATIONS

Local Notice to Mariners 65/20

Wick Channel Obstruction

Mariners are advised that during a recent bathymetric and dive survey we have identified an object in position $51^{\circ} 06' 54.448''$ N and $001^{\circ} 18' 56.9257''$ E. The object appears to be a 3mx3mx1.5m concrete block, which sits just east of the main channel and is highlighted on the chart below by a red circle.



Mariners passing through the Wick Channel should exercise extreme caution whilst manoeuvring through the Wick Channel and take into account the navigational hazard, which sits at 2.6m above chart datum.

Sarah West
Harbour Master

7th October 2020

Notices Remaining In Force:

- 08/19 – Decommissioned mooring equipment
- 68/19 – Structural Damage Pier Bravo
- 01/20 - Tide buoys (Revised)
- 35/20 - Lost Anchor Eastern Docks
- 53/20 – Pier C dolphin
- 58/20 – POWP lighthouse change of colour
- 65/20 - Wick Channel Obstruction